

Monitoring of limit value with display of closing force

With the function "Limit monitoring with closing force display" the machine load is measured and displayed on the control panel.

Your benefits

There are measured, the closing forces occurring in the process and visualized. This gives the operator an accurate view of the process. According to these values he will get information of machine settings and state of wear of the tool. The measured values are compared with the maximum load of the machine. The machine may stop to protect individual components of the machine against excessive wear, damage or destruction.

Available for machines

RDM 54K from #584_0300 RDM 70K from #716_0701 RDM 75K from #777_0501





